

P.U.(A) 289/86
FACTORIES AND MACHINERY (ASBESTOS PROCESS) REGULATIONS 1986
PART V - HANDLING AND DISPOSAL

Regulation 12. Handling and disposal of asbestos material.

(1) No asbestos material shall be despatched from or, so far as is practicable, received into a factory or warehouse, or be kept in a factory or warehouse, unless it is in a receptacle from which asbestos dust cannot escape or it is being transported within the factory in a totally enclosed system of conveyance.

(2) No asbestos material shall be disposed of as waste within a factory except in approved manner.

(3) All receptacles containing asbestos material in a factory shall be labelled as follows:

**"CAUTION-HANDLE WITH CARE
CONTAINS ASBESTOS MATERIAL
AVOID CREATING DUST".**