

**P.U.(A) 289/86  
FACTORIES AND MACHINERY (ASBESTOS PROCESS) REGULATIONS 1986  
PART XI - MISCELLANEOUS**

---

**Regulation 27. Smoking.**

- (1) The occupier shall ensure that no smoking is done or allowed in an asbestos processing area.
- (2) For the purpose of sub-regulation (1), the occupier shall post the following warning signs:

**"NO SMOKING - HEALTH HAZARD AREA".**

---