

**P.U.(A) 11/70**  
**FACTORIES AND MACHINERY (PERSONS- IN-CHARGE) REGULATIONS, 1970**  
**PART I - MACHINERY REQUIRED TO BE IN CHARGE OF PERSONS HOLDING**  
**CERTIFICATES OF COMPETENCY**

---

**Regulation 16. Death, sickness and leave of absence of person in charge.**

In the case of death, sickness or leave of absence of the person prescribed to be in charge of a machinery, or for any good and sufficient cause, the Chief inspector may, notwithstanding the provisions of these regulations, authorise the owner or occupier by a certificate in writing (which certificate may be revoked at the discretion of the Chief Inspector) to operate the machinery for a period not exceeding one calendar month without the person in charge thereof subject to such conditions as may be specified in the certificate.